

| Recall Ref | Make | Model | Concern | Numbers |
|-------------|------------|-----------------|--|--------------|
| R/2007/002 | Alfa Romeo | 147 | Amendments to vehicle handbook to inform owner of use of puncture repair kit and not space saver wheel. | 692 |
| R/2007/004 | Ford | Transit connect | Fuel tank straps may Corrode- no possibility of tank detachment | 15268 |
| R/2007/007 | Fiat | Croma | VIN plate may contain incorrect VIN number. | 259 |
| R/2007/023 | Ford | Fiesta/Fusion | Clutch pedal may not release. | 131273 |
| R/2007/027 | LDV | Maxus | Survey to check stub axle security. | 3581 |
| R/2007/028 | Chevrolet | Matiz Auto | Transmission assembly may leak - no UK cases precautionary check only. | 443 |
| R/2007/053 | Renault | Clio | Bonnet may open inadvertently due to inadequate maintenance - no design or construction deficiency identified. | 350000 |
| RM/2007/015 | Triumph | Bonneville T100 | Reminder to owners about wheel spoke security checks | not supplied |

| | | | | |
|--------------|-----------------------------|------------------------------------|---|--------|
| R/2007/057 | Renault Sports Technologies | Clio | Specially produced vehicles do not comply with spec and have been sold - owner contact. | 4 |
| R/2007/070 | Whale Tankers Ltd | Stjepvac 38/40 Tonne artic trailer | Trailer king pin mounting cracking - This is a maintenance issue and caused by abuse | 18 |
| R/2007/075 | Nissan | Almera | Headlight illumination may reduce | 42399 |
| NCA/2007/001 | Iveco | Eurocargo | Possible incorrect speedlimiter setting | 282 |
| NCA/2007/002 | Honda Motorcycles | VFR800 | Oil pipe may corrode and if ignored leak - maintenance issue. | 5973 |
| NCA/2007/003 | Vauxhall | Signum/Vectra | Precautionary measure - Instructions about safe parking. Warning sticker for sun visor. | 270000 |
| NCA/2007/004 | Mercedes Benz | Atego | Rear steer king pin securing nut torque setting check by dealers. | 111 |
| NCA/2007/005 | Mercedes Benz | Sprinter | Fit modified dipstick holder. | 1207 |
| NCA/2007/006 | Mitsubishi | Shogun | Water may leak from EGR cooler. | 19029 |

| | | | | |
|--------------|-----------|----------------------------------|---|-------|
| NCA/2007/007 | Volvo Car | XC90,New S80, V70 & XC70 | Product label does not have correct weight information to conform with legislation | 226 |
| NCA/2007/008 | Aprilia | RSV Mille | Service measure - correct rear brake bleeding procedures | 1500 |
| NCA/2007/009 | VW | Crafter | Speed display does not display KM/PH | 857 |
| NCA/2007/010 | VW | Transporter Sportline | Temporary spare wheel requires warning label regarding use. | 289 |
| NCA/2007/011 | Vauxhall | Antara | Trailer turn signal light may illuminate with stop lights if/when trailer fitted. | 468 |
| NCA/2007/012 | Landrover | Freelander 2 | Error on V5 - numbers of seat information. | 8632 |
| NCA/2007/013 | LDV | Various long wheel base vehicles | Handbrake connecting rod specification check. | 1645 |
| NCA/2007/014 | Honda | Civic 3 door and 5 door | Correct safe parking procedure information prior to recall of product to replace handbrake. | 80000 |
| NCA/2007/015 | Toyota | Verso | Driver error - gearbox may select neutral - operating instructions. | 3000 |

| | | | | |
|--------------|-------|--------|---|-------|
| NCA/2007/016 | Mazda | RX-8 | Reminder of maintenance/ checks of oil cooler pipes which may corrode | 25000 |
| NCA/2007/017 | VW | Passat | Reliability and durability research on corrosion effects on engine and suspension components. | 132 |