

Recall Ref	Make	Model	Concern	Numbers
NCA/2008/001	Suzuki	SX 1.6	Catalytic converter may fail - incorrect emissions	4394
NCA/2008/002	Nissan	Navara D40 -Pickup	Enhancement of SRS system - improve airbag deployment	23336
NCA/2008/003	Renault	Scenic	Mirror switch may overheat - window operation affected	70000
NCA/2008/004	SAAB	09-May	Owners manual has incorrect pages - jacking procedure	691
NCA/2008/005	Chrysler UK Ltd	Grand Voyager and Voyager	Brake pipes may deform during steering rack replacement - check only	812
NCA/2008/006	KTM	950 Adventure, Supermoto, 950 Superenduro and S/950	Inform owners of need of regular brake fluid changes	1305
NCA/2008/007	Mitsubishi	Outlander	Engine may stall when idling	1801
NCA/2008/008	Mitsubishi	carisma and Space Star	Wheel stud too long	459
NCA/2008/009	Mitsubishi	Grandis	Floor mat fixing kit not fitted	1893
NCA/2008/010	Mitsubishi	L200	Loss of power assistance	51953
NCA/2008/011	Mitsubishi	Shogun Sport	Loss of power assistance	15462
NCA/2008/012	Fiat	Sedici - Petrol models	Catalytic converter may not work correctly - emissions incorrect	888

NCA/2008/013	Izuzu Truck	N Series	Braking system may become inefficient - maintenance issue during stator replacement	7000
NCA/2008/014	BMW	F800	Incorrect length suspension spring fitted	4
NCA/2008/015	Renault Trucks UK Ltd	Magnum, Premium Kerax, Midlum and G Range	Cab movement increased by locking mechanism becoming seized	14275
NCA/2008/016	VW	Passat with diesel engine	Fuel pump may fail - high level power reduction	49000
NCA/2008/017	Suzuki motorcycles	GSX-R600	Incorrect power ECM fitted	21
NCA/2008/018	Toyota	MR2	ABS warning light may illuminate by fitment of accessory	7118
NCA/2008/019	Peugeot	407	Tyre inflation pressure of the space saver spare wheel is incorrectly displayed on the label situated on the front door pillar	211
NCA/2008/020	Mercedes Benz	Vito and Viano	Parking brake effectiveness - VOSA informed prior to any vehicles being delivered to dealers	179
NCA/2008/021	Lunar	Quasar EB and FB	Tyre pressures listed incorrectly in the handbook	170
NCA/2008/022	Ford	Transit fire extinguisher	Nozzle may become inoperative	2647

NCA/2008/023	LTI	TX4	Fuel may leak - new maintenance instructions during fire investigations	6000
NCA/2008/024	LTI	TX4	Continuing investigations into vehicle fire - survey	968
NCA/2008/025	Mazda	Mazda 2	Hub bearings may corrode	6469
NCA/2008/026	Mitsubishi	Colt	Information to users to use only existing wheel nuts when spare wheel is used	33647
NCA/2008/027	Volvo Bus	B series	Footbrake valve warning light and fault code reports - up date software	2300
NCA/2008/028	NAC MG UK Ltd	TF-LE500	Accelerator may detach - found on production - no vehicles delivered	267
NCA/2008/029	Mitsubishi	Outlander	Turbo hose may become disconnected	5250
NCA/2008/030	Mercedes Benz	Unimog	Tachograph contravenes EU directive	38
NCA/2008/031	Nissan	D22 - Pick up	Loss of engine power - durability issue - notification to users about correct maintenance	19354